



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, February 25, 2021	Project Contact:	Brian Clauto
Spread H: Franklin	ST13198-13262+62 ATWS 1055 AR-FR293.01	Weather:	Dry

Franklin	ATW	S 1055 R293.01		Weather:		Dry			
ACTIVE STAGE OF C	ONSTRUC	CTION: (Check all tha	at apply)						
☐ Tree Felling		Clearing/Grubbing		Grading	☐ Trenc	hing		Strir	nging/Welding
☐ Lowering/Backfi	ling \square	Final Grading		Temp. Stabilization	☐ Perm.	Stabilization	\boxtimes	Dorr	mant
							Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes		
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes		
3. Area	s of offsite	sediment deposition	observed	?				\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-II4 ECD's were in place and functioning at the designated crossing. 									
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A									
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A									
Recommended Corrective Action: N/A									

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Thursday, February 25, 2021

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Thursday, February 25, 2021

Figure 1: St13207+00 ECD's are in place and functioning.



 <u>Figure 2</u>: St 13210+80 Permanent style water bars are in place and functioning.



 <u>Figure 3</u>: Blanket matting has been installed on slip area near St13250.



 Figure 4: Designated crossing S-II4, ECD's are in place and functioning.

